



OFFICE OF DEFECTS INVESTIGATION (ODI)

Recalls - Search Results

1 Record(s) Displayed.

Report Date : **June 28, 2010 at 10:01 AM**

NHTSA CAMPAIGN ID Number: **10V276000**

Vehicle Make / Model:

BMW / K 1200 GT
 BMW / R 1200 GS
 BMW / R 1200 GS ADVENTURE
 BMW / R 1200 R
 BMW / R 1200 RT
 BMW / R 1200 ST

Model Year(s):

2007-2008
 2007-2009
 2007-2009
 2007-2009
 2007-2009
 2007

Manufacturer: BMW OF NORTH AMERICA, LLC

NHTSA CAMPAIGN ID Number: 10V276000

Mfr's Report Date: JUN 15, 2010

NHTSA Action Number: N/A

Component: SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected: 15532

Summary:

BMW IS RECALLING CERTAIN MODEL YEAR 2007 THROUGH 2009 R 1200 AND K 1200 SERIES MOTORCYCLES MANUFACTURED FROM AUGUST 2006 THROUGH MAY 2009. DUE TO THE CURRENT ROUTING OF THE FRONT BRAKE LINES, IT IS POSSIBLE THAT DURING RIDING, AND THEREFORE ASSOCIATED VIBRATION. THE BRAKE LINES COULD BE UNDER STRAIN. IF THE VIBRATION/STRAIN IS SIGNIFICANT, THE BRAKE LINE COULD SPLIT AND START TO DEVELOP A LEAK.

Consequence:

IF THIS GOES UNNOTICED, AND THE BRAKE FLUID RESERVOIR RUNS EMPTY, THE FRONT BRAKES COULD FAIL, INCREASING THE RISK OF A CRASH.

Remedy:

BMW WILL NOTIFY OWNERS AND DEALERS WILL INSTALL NEW BRAKE LINES, CONTAINING A "SLEEVE" ALONG A PORTION OF THE LINES FREE OF CHARGE. THE SAFETY RECALL IS EXPECTED TO BEGIN DURING JULY 2010. OWNERS MAY CONTACT BMW AT 1-800-525-7417.

Notes:

OWNERS MAY ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov) .